

Toxic vapour (HCl) emissions due to overflow of a proportioner in a chemical plant

16th October, 1991

**Chalon-sur-Saône (Saône-et-Loire)
France**

Fine chemistry (batch)
 Management of change
 Installation design
 Procedures
 Automated mechanisms
 Risk mitigation
 measures (bypass)
 Organisation / anomaly
 description

THE FACILITIES INVOLVED

The site:


The plant, which was employing a staff of 28, was located in an industrial zone 1,500 m south-east of the city centre. It was manufacturing liquid organic peroxides, either by means of direct action of hydrogen peroxide on an acid chloride or else via tert-butyl hydroperoxide (T.B.H.P.).

The facility, which had to submit operating permit applications, was as of 1st June, 1991 required to comply with the Seveso I Directive for peroxide storage. As such, this plant was ordered to furnish a safety report and an internal operation plan by 31st December, 1993.

The nearest residences were located 200 m east of the site.


The specific unit involved:

The workshop, which had been operating for 25 years, comprised 2 octanoic acid chloride production chains running in parallel. The chemical reaction being implemented was practically athermal, i.e.:



The acid, which needed to gradually reach a temperature of 50°C, was introduced into a reactor the day prior. The next day, 466 kg of phosphorus trichloride (PCl₃) were added through a proportioner. The gravity-induced flow took 30 to 40 minutes without requiring any stirring; all of the acid was able to react within 5 hours at 60°C. Once the reaction was complete, the reaction mixture was cooled at 25°C until the following day. The phosphoric acid and acid chloride produced were separated by gravity when draining the reactor. Both these products were then prepared for sale.

Placed above the reactor (see schematic diagram on p. 2), the proportioner was connected by a pipe and pump to a 22-m³ storage zone located 20 m outside from the workshop. This pump was activated for PCl₃ transfer to the production chains as well as all transfer operations for cisterns supplying the site's storage facilities. Hence, the maximum pump flow rate (300 l/min), designed to accommodate these transfers, was too high compared to both the proportioner's actual capacity (500 l) and the quantity needed to be introduced per batch (293 l, i.e. less than 1 minute of transfer).



THE ACCIDENT, ITS CHRONOLOGY, EFFECTS AND CONSEQUENCES

The accident:

The accident occurred upon restarting a portion of the installations after a 4-month plant shutdown and a series of many blank tests.

A well-experienced technician started his shift at 7 am. From the installation's pneumatic control console, he activated the PCI₃ pump in order to fill the proportioner on the 1st chain. He proceeded by verifying the level (using a glass tube and mirror), stopped the pump and then adjusted the chloride flow rate into the reactor (which had been prepared since the day before, in accordance with current procedure). He had returned to the plant's ground floor to prepare to drain the reactor on the 2nd chain, whose synthesis operation had been completed, when he was sprayed by PCI₃ (at around 7:10 am) that had overflowed from the proportioner subsequent to an unscheduled restart of the PCI₃ transfer pump.

The technician immediately left the building to activate, from the outside, the pump emergency shutoff button. A second technician verified that the pump had been stopped and removed the fuses from the pump's electrical control circuit to ensure that the pump had been turned off definitively.

The maintenance electrician, who was also a member of the site's emergency intervention team, wore the emergency gear and, equipped with a rope, entered the workshop filled with white acid (HCl) fumes to secure the facility by closing all manual and automatic valves on both installations.

PCl₃ had spread into the plant and then into the sewer system. Given the lack of a specific written protocol in the event of accident, it was decided to flood the sewer lines using fire nozzles, but this step wound up exacerbating the phenomenon of phosphorus trichloride hydrolysis. The ensuing toxic cloud, composed primarily of hydrochloric acid, headed towards the city centre due to unfavourable meteorological conditions in the presence of fog.

Local fire-fighters, who had received many emergency calls, provided treatment to the first intoxicated victims around 7:40 am. They telephoned 3 industries located in the zone likely to be the source of this toxic pollution; the plant operator confirmed incident occurrence at 8 am. Formation of an emergency unit was initiated and fire crews performed an analysis of the atmospheric pollutants emitted. Wind had dissipated the gaseous cloud within an hour. The local Prefecture issued a press release, and the city of Chalon requested its residents to contact a physician or the SAMU emergency medical services in cases of breathing difficulties, eye irritation, etc.

Consequences of this accident:

The effects of this accident were observed over a radius extending 1,500 m from the point of emission. The 2 employees exposed were hospitalised for observation and 17 individuals from outside the plant contacted emergency services; 11 of them were admitted to the emergency room for testing, and all were released a few hours later.

pH recordings at the site outlet revealed a significant drop in pH (pH = 3) between 7:30 and 8:30 am, yet no fish mortality could be detected.

CHALON
UN NUAGE TOXIQUE SURVOLE LA VILLE

La gorge irritée malgré un mouchoir sur la bouche et les yeux embués de larmes, il était impossible hier matin de ne pas ressentir les effets de l'émanation d'un produit toxique dans l'air ambiant.

CHALON. — Une grande partie de la population chalonnaise était surprise pour sa première fois de son hôpital à une pollution industrielle de grande envergure. Et ce dès six heures par à la pollution, il s'en est dégage une odeur qui est caractéristique de certains produits chimiques. Les premiers symptômes sont apparus à 7 heures 40. Les personnes se rendant à leur travail, à la boulangerie ou au bureau de tabac, les symptômes ont été constatés. Les premiers symptômes sont apparus à 7 heures 40. Les personnes se rendant à leur travail, à la boulangerie ou au bureau de tabac, les symptômes ont été constatés.

Débordement
7 heures 30. Un robinet sur le réacteur s'est ouvert. Le contenu du réacteur s'est déversé dans le canal. Le produit chimique est devenu blanc et épais. Les personnes présentes ont été évacuées. Les secours sont arrivés à 8 heures.

Vol interdit
Plus de trois cents tentatives de cambriolage ont été effectuées dans les locaux commerciaux depuis des semaines. Les services de sécurité ont été renforcés.

The European scale of industrial accidents

By applying the rating rules applicable to the 18 parameters of the scale officially adopted in February 1994 by the Member States' Competent Authority Committee for implementing the 'SEVESO' directive on handling hazardous substances, and in light of information available, this accident can be characterised by the four following indices:

Dangerous materials released		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Human and social consequences		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Environmental consequences		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Economic consequences		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

The parameters composing these indices and their corresponding rating protocol are available from the following Website: <http://www.aria.developpement-durable.gouv.fr>.

In the presence of water (even simply through airborne humidity), approximately 489 l of hydrochloric gas were formed per kg of PCl_3 . According to operator estimations, 267 litres would have overflowed into the plant, i.e. 530 kg, which in turn generated a hydrochloric acid volume of nearly 260 m³. The hazardous substances released index therefore reached a level "3" (parameter Q1 equal to 2.6% of the Seveso tier for PCl_3).

The human and social consequences index was scored a "3", given that 2 employees and 11 members of the public had been slightly intoxicated.

Since no environmental consequences directly corresponding to the scale parameters had been reported, this index was set equal to "0".

Given the lack of information available on the amounts of eventual property damage or production losses, the economic consequences index could not be rated.

THE ORIGIN, CAUSES AND CIRCUMSTANCES SURROUNDING THIS ACCIDENT

The investigation revealed a whole set of deficiencies, relative to both physical and organisational aspects:

Installation design

- Work station ergonomics were not well adapted. More specifically, the liquid level was difficult to distinguish inside the proportioner (requiring use of a mirror), and the control cabinet was not visible from the lower part of the installations.
- An (overly) complicated control circuit included many time lags capable of generating interactions. The only pump used for the PCl_3 transfers was being controlled by a set of switches distributed at 4 different points, none of which were mutually visible.
- The maximum pump flow rate (300 l/min) was too high compared to the proportioner's actual capacity (500 l) and the quantity to be introduced per batch (293 l, i.e. less than 1 minute of transfer!), thus forcing the technician to hurry to turn off PCl_3 supply prior to triggering the high level alarm.
- Due to the excessive PCl_3 supply flow rate (see above point), monitoring of the PCl_3 quantity introduced into the proportioner was too imprecise and the installation regularly switched into security mode. To avoid this phenomenon, the safety function was bypassed by altering the prescribed point to "end pump filling".
- Despite the presence of a highly corrosive atmosphere, the relay cabinet was not sealed. The control circuit copper pipes were covered with salt deposits, which increased the risk of property degradation.
- The installations using PCl_3 were not adequately confined. A manhole on the proportioner was blocked by an unfastened flange despite the indicated design locations. The PCl_3 that spread wound up reaching the sewer network via a low point sump in the building (inside a plant without retention).

Maintenance / repair phases

- Both safety mechanisms associated with the proportioner's level probe were malfunctioning, the first shunted following a series of repeated activations (see point under "Installation design" above), while the second (which was a malfunctioning or inaudible "proportioner high level" sound alarm) was never repaired.
- An orifice, used to limit the proportioner supply flow rate at the source to 50 l/min and provide the time necessary for the technician to handle reagent loading, had disappeared several years prior for no apparent reason. Moreover, an orifice in the tank's overflow duct reduced, again for no apparent reason, its diameter from 80 to 20 mm. The overflow discharge rate was thus limited to 23 l/min, a value much lower than the pump flow rate, which as a result prevented the overflow from performing with an activated safety function. The

operator explained these modifications by an eventual assembly error committed during maintenance. Such modifications did not appear on the installation drawings and were seemingly unfamiliar to the site's technical staff.

- A detected air leak the day prior on the pneumatic control circuit had not been repaired before restarting the unit. A temporary modification was provided instead on one of the installation's control boxes. A "fill" pushbutton and its cell, which were out of stock, had been replaced on a "floating installation" by a dial with a different operating mode. This modification, performed without updating the operating guidelines and without analysis of its potential impact on safety, led to circumventing 2 successive "AND" gates on the automaton.

Organisation / Protocol / Supervision

- The operating plans and protocols were not systematically updated, especially when introducing modifications.
- No modification management procedure had been formalised for the preparation, monitoring or verification of equipment modifications.
- The protocols did not outline appropriate conduct in the event of a degraded situation, such as the spreading of a hazardous product like PCl_3 . The water used during the emergency intervention had, as a consequence, magnified the size of the toxic cloud.
- Apparently, the hierarchy remained unaware of many plant malfunctions. Such was the case with the orifice modifications, as well as the alteration of recommended operating points and improper functioning of the sound alarm.
- A similar incident (unscheduled pump restart) had previously occurred at the same site a few years prior during a transfer step, though without seeming to initiate any special remedial actions of modifying the installations or their operating system (due to the lack of exploitation of experience feedback).

ACTIONS TAKEN

The site operator decided to discontinue this production line.

LESSONS LEARNT

The accident arose on an older installation subsequent to several modifications performed without adequate information provided to users or management. Moreover, many human errors were committed, some of which made possible due to poor ergonomics designed into the installations and their control systems.

Given the remarks delivered regarding the pneumatic control devices (circuit complexity, reliability of certain components, location of the control cabinets, etc.), special attention must be paid to the following:

- consequences stemming from the eventual pollution of the air control and command circuits;
- the risks of malfunction in a corrosive atmosphere among certain devices that may not be sufficiently protected (in particular the pneumatic cells);
- stable vs. unstable states of the automated mechanisms, in order to take into account time lags or the eventual effects of a simultaneous action on several switches. In the present case, the operator had noted that a transfer pump restart after shut-off was capable of occurring when 2 technicians intervened simultaneously;
- ageing of certain components (e.g. cells) that may cause malfunctions capable of compromising installation safety.

This accident highlights, in addition to the importance of an effective installation design (pumps with capacities different for the storage and plant supplies, buildings under retention, control system ergonomics, etc.) and their maintenance over time, the need for strict organisation with oversight of actual applications and a strong involvement from facility executives (safety management system subject to executive review, internal emergency plan, change management procedures, protocols, etc.). In fact, the anomaly observed by the technician necessitating, subsequent to onsite works, running to a location where he could shut off the pump in time should have been targeted for further analysis (as a precursor). Similarly, the repair works should have been officially accepted and inspected, a step that would have allowed noticing the poor orifice assembly.